CPI PRODUCT BULLETINS
FOR MEDICAL X-RAY DEVICES

PB20INDIQ240B   Rectifier Board Assembly Improvements and Changes

PB20INDIQ239   Release of New Mezzanine Board for Indico IQ®

PB19CMP238   improved Generator Control Board and New AC Contactor for CMP 200® DR X-ray Generator

SB19INDIQ237   Indico IQ® GCB Setting for Agfa DR800 for Potential No Exposure Condition

SB19INDIQ236   Indico IQ® Software Update for Fluoro Contactor Issue

PB19GEN235   StarQ Touch Screen Console with Windows 10

SB19GEN234   Dual Speed Starter Tab - 24

SB19IND233   Indico 100® with IBA High Resolution DAP

PB19CMP232   Change in CE Mark Notified Body for CPI Medical Products

PB19CMP231   Changes for EMC Performance Improvement

PB18CMP228   Single Inverter Board

PB18GEN226   New CPI Medical Product Certification TUV

SB18INDIQ224   Indico IQ® Automatic Brightness Stabilization (ABS) Hardware Gain Adjustment

SB18CMP223   Update for the F8 & F9 Fuses of the High Voltage Auxiliary Board (208/230 VAC, PN73944599)

PB17GEN222   SMT Filament Board

PB17IQ221   Dual Speed Starter Board (DSS2) 90313203 Release for DSS or LSS Mode of Operation

SB17IQ220   Generator Firmware 90623700 Rev. T Update

This page will be updated and changed as new Bulletins are released. Previously released Bulletins are available by submitting the request form asking for a listing of older Bulletins.